

TI_2122: Connector latch for I/O board



iCombi Pro / Classic



12/10/2021

Reason:

Due to the globally strained delivery situation of coded plugs, uncoded plugs will be installed in isolated units from 01/09/2021.

To ensure that the connectors are still in the correct position on the I/O board, a connector latch is also attached to guarantee the exact position of the connector.

This has no impact on the function of the units.

Affected units (unit size and unit type):

iCombi Pro / iCombi Classic


- 6-1/1
- 6-2/1
- 10-1/1
- 10-2/1
- 20-1/1
- 20-2/1

Affected components

Component	Article number
I/O module with metal cage	42.00.280
I/O module cpl.	40.05.919P

Repair/modification:**Variants:**

1. With connector latch for I/O board
2. Without connector latch for I/O board



>> Both variants are available on the market and are correct.