

TI_2131: Component required for installation- Combi-Duo unit, left-hinged



Combi Duo E



08/11/2021

Reason:

If the Combi-Duo 60.73.991 1/1 and 60.74.725 2/1 is installed in conjunction with a left-hinged unit installed at the bottom, the panel 60.75.864S for 1/1 and 60.75.867S for 2/1 must be ordered. The gaps (see graphic) for correct installation are not present for left-hinged units.

This only affects sets produced before 01/12/2021. This is invoiced via our service call (good-will).

Affected units (unit size and unit type):

iCombi electric, left-hinged

- 6-1/1
- 6-2/1
- 10-1/1
- 10-2/1

Required components

Component	Article number
Combi Duo E 1/1	60.75.864S
Combi Duo E 2/1	60.75.867S


Repair/modification:

What costs are covered?

- Delivery of the following components:
 - Combi Duo E 1/1: Article number:60.75.864S
 - Combi Duo E 2/1: Article number:60.75.867S

Photos/drawings/other:

Required component for installation of a left-hinged unit.



Current component that can not be used for installing a left-hinged unit.

