


TI_2211: iVario hand shower drips in park position

**Reason:**

In park position, the hand shower may drip slightly due to the two possible settings (jet and spray). This condition does not indicate a technical defect, but is due to the residual quantity of water in the hand shower head.

Repair/modification:

The dripping in park position can be avoided (1) by shaking the hand shower after use and positioning it vertically in the holder so that the spray opening points upwards at an angle (2).

It is therefore not necessary to replace the hand shower. Replacement under warranty will not be offered.

Photos/drawings/other: