

TI_2221: Tightening torque 3 Nm



All iVario



Standard



18/11/2022

Topics

Tightening torque contactor.

Affected product/accessories

iVario 2-XS, 2-S, 2-S P, L, L P, XL, XL P

Affected components


Contactor

Required components

-

General information

To prevent a fault on the cable crimping and to prevent overheating at the contact points, screw fittings must be tightened to 3 Nm. We would also like to point out that, during the installation of the unit, the input and output screw connection of the contactor must be retightened to 3 Nm.



NOTE:

No further action is required.