

## TI\_2314: Change to the sensor module



iVario 2-S P, iVario L P, iVario XL P



-



-



19/05/2023

## Topics

To further enhance the reliability of the units with pressure option, the sensor module and the 20 mbar and 350 mbar pressure switches have been modified.

## Affected product/accessories


iVario 2-S P

iVario L P

iVario XL P

## Affected components

Previous design:



New design:



## General information

In the new design, the pressure sensor is located between the two pressure switches. The pressure switches are held in place by two clamps and a support plate and are no longer screwed tight. This significantly increases the pressure measurement area.

## NOTE:

No further action is required.