

TI_2317: Adaptation of door contact switch

 iCombi Pro / iCombi Classic 6-1/1 - 10-2/1

 ---

 ---

 28/06/2023

Topics

In response to worldwide feedback, the door contact switch has been revised to prevent moisture in the connection.

From now on, there will be a continuous cable from the door contact switch to the pump board. This avoids an intermediate connector as a possible source of fault.

Affected product/accessories

- iCombi Pro & iCombi Classic Electric and Gas
- 6-1/1
 - 6-2/1
 - 10-1/1
 - 10-2/1

Affected components

Component	Article number
Door contact switch 1/1	40.07.962P
Door contact switch 2/1	40.08.018P

General information

NOTE: No active component replacement is necessary.

Old door contact switch up to 06/2023: Art. no.: 40.06.664P



New door contact switch from 07/2023: Art. no.: 40.07.962P (1/1) or 40.08.018P (2/1)

As a service part, the cables are available in two different lengths for unit sizes 1/1 and 2/1 for tabletop units.



NOTE: In the event of a faulty pump board, check for possible damage/humidity on the old door contact switch.