

TI_2125: Adaptation of service part "Drain valve drain SCC cpl." without adapter cable



SelfCookingCenter®



24/04/2026

Topic

No adapter cable (40.04.393P) is supplied with the drain valve drain SCC cpl. (56.00.618S).

The adapter cable can still be purchased as a service part in small quantities.

This modification has no impact on the function of the units.

Affected product/accessories

All SelfCookingCenter® models

Affected components

Component	Item number
Drain valve drain SCC cpl.	56.00.618S
Adapter cable for drain valve	40.04.393P

General information

Because the adapter cable is already installed in the unit, it does not necessarily have to be replaced.

You can continue to use the existing connector.

If the old adapter cable is faulty, order a new adapter cable under "Affected components" using the item number.

Revision Log

Changes from previous version of this document:

- The item number of the drain valve drain SCC cpl. has been changed

NOTE:

No further action is required.