

TI_2127: Adaptation service part "Control transformer T1 with 7-pin connector strip"



see affected units



12/10/2021

Reason:

Due to the globally strained delivery situation for connectors and connecting cables, the "7-pin connector" (40.02.402) will no longer be supplied with the "Control transformer T1 with 7-pin connector strip" from (87.01.297) 01/10/2021.

The "7-pin connector" (40.02.402) will still be available to purchase in small quantities as an individual service part.

This modification has no impact on the function of the units.

Affected units (unit size and unit type):

- SelfCookingCenter ® Index H
- CombiMaster ® Plus
- VCC Index H

Required components

Component	Article number
Control transformer T1 with 7-pin connector strip	87.01.297
7-pin connector	40.02.402

Repair/modification:

Because the "7-pin connector" (40.02.402) is already installed in the device, this connector does not necessarily have to be replaced. This means that you can continue to use the existing connector.

If the old connector is faulty, order a new "7-pin connector" under "Affected components" using the article number.