

TI_2128: Wrong castor for mobile oven rack 20-1/1



iCombi Pro/Classic



29.11.2021

Reason:

We regret to inform you that due to a supplier's error, we have equipped mobile over racks for 20-1/1 with the wrong castors.

As a result, the parking brake is applied to the base frame of the mobile oven rack and the roller can lock or the HGW can no longer be manoeuvred.

Affected devices (device size and device type):

iCombi Pro / iCombi Classic:

20-1/1

Affected components

Article number	Device size
60.21.245	Mobile oven rack 20-1/1 (62 mm busbar spacing)
60.21.287	Mobile oven rack 20-1/1 (15 x 1/1 GN)
60.21.288	Mobile oven rack 20-1/1 (16 x 1/1 GN)
60.21.291	Mobile oven rack 20-1/1 (HeavyDuty / Marine)
60.21.292	Mobile oven rack 20-1/1 (Bäcker mobile oven rack 16 x 400x600 mm)
60.21.293	THGW 20-1/1 (plate mobile oven rack for 60 plate to 30 cm)
60.21.294	THGW 20-1/1 (plate mobile oven rack for 50 plate to 31 cm)
60.21.331	Mobile oven rack 20-1/1 (default)

NOTICE

All mobile oven racks dated 32/2021 and 33/2021 listed above may be affected.

**Remedy/Change:**

Please exchange the mobile oven rack castors for the castor provided. Damage the old castor so that it can no longer be used and document this with pictures.

You need the castor twice.

Art. no.: 60.74.681P – Castor with brake 125 mm

The conversion of the castors is described in MI_1902 and these instructions must be followed. You can charge RATIONAL for the service call in accordance with the ServiceCall/ServiceDesk instructions.

The corresponding instructions can be found =>**HERE**<= under ServiceCall Information or ServiceDesk Information.