

TI_2130: Colour differences on solid state relays (SSR) - information



Solid state relays



01/11/2021

Reason:

Due to the ongoing supply shortages in many areas, solid state relays (SSR) are temporarily unable to be produced as usual with blue plastic housings.

Repair/modification:

For this reason, you will find colourless SSRs on the devices on the market. This has no impact on the function.

Certifications according to UL and VDE are not affected by the colour changes and remain valid.

Photos/drawings/other:

