

TI_2205: Adjustment gauge – door catch adjustment aid – iCombi floor unit



iCombi floor unit



23/03/2022

Subject

In order to ensure that the correct distances have been set on the lock on the iCombi floor unit, we have developed a "Door catch adjustment aid" Art. no. 91.01.220P This is now available as a service part.

Affected product/accessories



- iCombi
- 20-1/1
 - 20-2/1

Affected components

Component	Article number
Door catch adjustment aid	91.01.220P

General information

Picture of the door catch adjustment aid



NOTE:

Further information can be found in MI_2101_Unit leak cabinet door – troubleshooting_M.



LINK MI_2101