

TI_2209: New VarioCookingCenter® pan lift cylinder



Standard



22/04/2022

Reason:

Due to the global supply situation, the pan lift cylinders of the VarioCookingCenter® units 211–311 were modified with production index A, B, G and H.

Affected units (unit size and unit type):

VCC 211–311 Index A, B, G

VCCM 211–311 Index H

Repair/modification:

The pan lift cylinder, item number 40.04.932, which is used for VCC 211–311 Index A, B, G and VCCM 211–311 Index H, is no longer available and will be replaced by two new item numbers. Since item number 40.04.932 is replaced by 2 different pan lift cylinders (depending on the production index of the units), it has been blocked and can no longer be ordered.

The new item numbers are as follows:

- VCC Index A, B, G 40.07.748P
- VCCM Index H 40.07.749P

You can find these item numbers in the service parts catalogue for the equipment in question according to their manufacturing index.

These two new engines will be available from the beginning of May 2022.