

TI_2214: Cleaning the jet regulator

**Reason:**

The automatic water refill of the iVario units calcifies over time and impairs the water supply. Depending on the level of soiling and water hardness, the jet regulator must be cleaned occasionally, but at least once a year.

Repair/modification:

The jet regulator can be unscrewed using the service key provided (which will be included in every starter kit) for cleaning purposes. Clean the jet regulator with vinegar water and rinse it with water.

Tip: Place the jet regulator in a container with white vinegar overnight.

After cleaning, the jet regulator can be re-inserted with the service key.

Jet regulator service key: Article no. 50.02.319P.

Photos/drawings/other: