

TI_2217: Adjustment of stop buffer



iCombi Pro and iCombi Classic electric and gas 20-1/1 and 20-2/1



04/07/2022

Subject

In order to prevent the stop buffer Art. no.: 24.05.002P from sticking to the front wall due to vacuum pressure or soiling, which could lead to loss, the stop buffer was adjusted.

Affected product/accessories

iCombi Pro and iCombi Classic electric and gas

- 20-1/1
- 20-2/1

Affected components

Component	Article number
Stop buffer	24.05.002P

General information


The article number for the stop buffer remains unchanged.

From now on,


- for newly produced units
- and in service,

only new stop buffers will be available.

The stop buffer is in the following position:



New stop buffer:



Previously used stop buffer:



NOTE:

No other actions are required.