

TI_2303: UltraVent (Plus) XS control PCB

 iCombi Pro; CombiMaster Plus; SelfCookingCenter

 28/04/2025

Topic

Due to a component adaptation, a new control PCB will be installed in the UltraVent / UltraVent Plus XS from February 2023.

This changeover results in a new service part with the article number 42.00.412P.

Up to January 2023, the control boards with the following item numbers were installed:

- 42.00.050P
- 42.00.274P
- 42.00.284P

Affected units (unit size and unit type):

UltraVent / UltraVent Plus: XS

Affected components


Overview control boards

Article number	Corresponding hood	Voltage
42.00.050P	SelfCookingCenter, and 6-2/3 units until 01/2023	230 V
42.00.274P	SelfCookingCenter, and 6-2/3 units until 01/2023	120 V
42.00.284P	For all 6-2/3 combinations up to 01/2023	230 V
42.00.412P	From and 6-2/3 units from 02/2023	120 V, 230 V

Up to January 2023, the control boards with the following item numbers were installed:

- 42.00.050P
- 42.00.274P
- 42.00.284P

The control board is also available as a service part.



From February 2023, the following control board with article number 42.00.412P is installed:
The control board is also available as a service part.



Revision Log

Changes from previous version of this manual:

The following has been added to the Technical Information sheet:

- Article number and graphic of the control board installed up to January 2023.

NOTE:

No further action is required.