

TI_2310: Material adjustment on the drain opener



iCombi Pro / iCombi Classic 6-1/1 -
10-2/1



22/05/2023

Topics

Following a material adjustment on the drain opener (repair kit for drain opener door drip pan, item no.: 87.01.917S), the drain opener is now made of the same material as the door drip pan. The collared bushings are omitted as a result of this change.

Affected product/accessories

iCombi Pro / iCombi Classic Electric / gas


- 6-1/1
- 6-2/1
- 10-1/1
- 10-2/1

Required components


Component	Article number
Repair kit drain opener door drip pan	87.01.917S
Door drip pan 1/1	24.05.499S
Door drip pan 2/1	24.05.500S

General information

Installation position



Old drain opener up to 06/2023




New repair kit drain opener from 06/2023

No active component replacement is necessary.

From 06/2023, the new drain opener repair kit with item no.: 87.01.917S, the door drip pan 1/1 (incl. drain opener) item no.: 24.05.499S and the door drip pan 2/1 (incl. drain opener) item no.: 24.05.500S is available for service parts.

All affected components are backwards compatible.



NOTE:

No further action is required.