

TI_2318: Adaptation of circulation pump – stainless steel housing as a service part

 SelfCookingCenter

 ---

 ---

 28/06/2023

Topics

Due to the pump adaptation (see TI_2308), the stainless steel housing is no longer included as standard with the circulation pump with the SelfCookingCenter (Index E-I).

In the event of a faulty stainless steel housing, it can now be purchased as a service part.

Affected product/accessories

- SelfCookingCenter Electric & Gas
- 6-1/1
 - 6-2/1
 - 10-1/1
 - 10-2/1
 - 20-1/1
 - 20-2/1

Affected components

Component	Article number
Housing circulating pump tabletop unit	87.01.992S
Housing circulating pump floor unit	87.00.423


General information

In a service case:

The stainless steel housing of the circulating pump UP30 with the SelfCookingCenter can now be purchased as a separate service part.


Table-top unit

- Graphic representation of a pump housing for a tabletop unit Art. no.: 87.01.992S.



Floor unit

- Graphic representation of a pump housing for a floor unit Art. no.: 87.00.423.



NOTE:

No further action is required.