

TI_2508: Glass pane support

 iCombi Pro 6-2/1 & 10-2/1, SelfCookingCenter 6-2/1 & 10-2/1

 02/07/2025

Topic

A glass pane support (1) has been developed in response to frequent feedback regarding pane corrosion and the associated pane deflection.

This support does **not** prevent glass pane corrosion. However, the support counteracts deflection when the glass pane package is closed.



Component	Article number
Horizontal spacer	24.06.171P

Affected product/accessories

The horizontal glass pane support will be installed from 05/2025 on the following units:

iCombi Pro Electric and Gas

- 6-2/1
- 10-2/1

The vertical glass pane support will be installed from 05/2025 on the following units:

iCombi Pro Electric and Gas


- 10-1/1
- 10-2/1

Notice: The glass pane supports cannot be retrofitted on older doors (before 05/2025) and older glass pane packages (before 05/2025).

Affected components

- iCombi Pro/SelfCookingCenter 6-2/1:
- The glass pane package with item no.: 24.04.896 will be replaced from 05/2025 by the glass pane package with item no.: 24.06.269.
- iCombi Pro/SelfCookingCenter 10-2/1:
- The glass pane package with item no.: 24.04.898 will be replaced from 05/2025 by the glass pane package with item no.: 24.06.270 .

General information



NOTE:

No further action is required.