

TI_2607: Adjustment of Pressure Sensor Service Part Incl. Moisture Hoses



iCombi Pro / iCombi Classic / iHexagon



01/07/2026

Topic

After replacing the pressure sensor, the associated moisture hoses must also be replaced for the moisture control to function correctly.

Starting June 2026, RATIONAL will ship the pressure sensor together with new moisture hoses in the event that service is necessary.

Modification Instructions MI_2606 are also enclosed. This document describes how to correctly route the moisture hoses.

Affected product/accessories

iCombi Pro / iCombi Classic / iHexagon

Required components

Component	Article number old	Article number new
Pressure sensor, 3 mbar, incl. hose set LM1; A	3017.1011	87.02.131S
Pressure sensor, 5 mbar, incl. hose set LM1 LM2; B-E(E), B-C(G)	40.06.801	87.02.132S
Pressure sensor, 5 mbar, incl. hose set LM1 LM2; F G(E)	40.06.801	87.02.133S
Pressure sensor, 5 mbar, incl. hose set LM1 LM2; D-E(G)	40.06.801	87.02.134S
Pressure sensor, 5 mbar, incl. hose set LM1 LM2; F G(G)	40.06.801	87.02.135S

NOTE:

No further action is required.