

TI_2312: Safety information RATIONAL VarioCookingCenter®



VarioCookingCenter®



21/04/2023

Topics

Important safety information for all RATIONAL VarioCookingCenter® **series no. 8007287 (E11VH10098007287) - 8047539 (E13VJ20068047539).**

Affected product/accessories

VarioCookingCenter®

General information

Your safety and the reliability and durability of our units are our top priority. During our continuous product monitoring, we have found that, in rare cases, the pan can move independently on units from the VarioCookingCenter® product series. This could potentially lead to uncontrolled escape of hot food, which could result in injury to persons nearby.

In this respect, please note the following safety instructions:

To rule out the unlikely event of danger, the software VCC-01-02-04.7 must be installed during the next service or visit to customers with a unit from the above-mentioned VarioCookingCenter® product generation.

With this software, the scroll wheel must be pressed at the same time in order to move the pan.

This function is also implemented in the iVario product currently in series production.

If you have any further questions, please do not hesitate to contact us by e-mail: service_uk@rational-online.com

NOTE:

No further action is required.