

TI_2315: Replacing the iVario pulse generator



All iVario



16/06/2023

Topics

Since mid-May, all iVario units have been fitted with new pulse generators from a different manufacturer.

Affected product/accessories

All iVario

Affected components

The new pulse generator will have a new article number: 40.07.493P



General information

Unlike its predecessor, the new pulse generator can be installed in all iVario units.

NOTE:

No further action is required.