

TI_2323: Adaptation of SelfCookingCenter/CombiMaster Plus door handles



SelfCookingCenter, CombiMaster Plus



31/10/2023

Topics

Due to a material change, all door handles of the SelfCookingCenter/CombiMaster Plus will be gradually converted to the door handles of the iCombi.

This change means that, for

- SelfCookingCenter / CombiMaster Plus units and
- iCombi units,

identical door handles will be installed in future in the event of a service.

Affected product/accessories

SelfCookingCenter; CombiMaster Plus

- 6-2/3
- 6-1/1
- 6-2/1
- 10-1/1
- 10-2/1
- 20-1/1
- 20-2/1

Affected components

Affected units	Article number - old	Article number - new
Tabletop unit - SelfCookingCenter	24.02.923P	24.04.083P
SelfCookingCenter floor unit	24.02.920P	24.04.065P
Tabletop unit CombiMaster Plus	24.00.153P	24.04.084P
Floor unit CombiMaster Plus	24.00.143P	24.04.081P
Tabletop unit SelfCookingCenter OEM	24.03.470P	24.04.439P
Floor unit SelfCookingCenter OEM	24.03.471P	24.04.441P

NOTE:

No further action is required.