

TI_2402: Omission of the centre cover of the installation area at the rear.

 iVario 2-XS & iVario Pro
2-S

 ---

 ---

 26/02/2024

Topic

The centre cover for the rear installation area is omitted for series production and is no longer installed.

Affected product/accessories

- iVario
- 2-XS
- iVario Pro
- 2-S

Affected components

Component	Article number
Centre cover rear installation area	12.02.684P


General information

The centre cover for the rear installation area will no longer be installed from 15/02/2024.

This improves the air flow and reduces the temperature in this area. The centre cover is therefore not part of the unit.


The cover for the rear installation area Art. no.: 12.02.684P is no longer available as a replacement part and has been given the status "No longer available, without replacement".

Old delivery state:



1 | TI_2402: Omission of the centre cover of the installation area at the rear.

New delivery state:



NOTE:

No further action is required.

