

TI_2605 SelfCookingCenter incremental encoder - changed spare part numbers



SelfCookingCenter



09/03/2026

Topic

This Technical Information sheet describes a change in the spare part assignment of the **incremental encoder for the SelfCookingCenter**. It applies to the **1st generation (year of manufacture 2004-2011)** and to the **2nd generation (year of manufacture 2011-2020)**.

The **previous incremental encoder** Item no.: 40.00.404P was used as a common spare part for both generations, but is no longer produced and can no longer be ordered.

This article is being replaced by two generation-specific service parts:

Component	Item number
SelfCookingCenter 1st generation (2004-2011): Incremental encoder	40.06.970P
SelfCookingCenter 2nd generation (2011-2020): Incremental encoder	40.07.493P

The service parts catalogue will be adapted accordingly for the **2nd generation SelfCookingCenter**; in the future, the Item no.: 40.07.493P will be listed there. A shared replacement item is no longer possible because the design of the incremental encoder has changed. The incremental encoder Item no.: 40.07.493P is larger and does not fit mechanically into the front panel of the **1st generation SelfCookingCenter**. Automatic assignment in the service parts catalogue is therefore no longer possible. When attempting to order the previous incremental encoder, Item no.: 40.00.404P an error message will appear in the future.

NOTE:

No further action is required.