

TI_2204: Design change of silicone hose with clamps



iCombi 20-1/1 & 20-2/1



02/03/2022

Subject

Due to a design change in the silicone hose with clamps Art. no.: 56.01.688S, it will be replaced from 02/03/2022 with pipe elbows with hose clamps Art. no.: 56.01.979P

Affected product/accessories

iCombi

- 20-1/1
- 20-2/1

Affected components

Pipe elbow with hose clamps Art. no.: 56.01.979P replaces silicone hose with clamps Art. no.: 56.01.688S

General information


Kit of components installed until 01/03/2022:

- Silicone hose with clamps Art. no.:56.01.688S



From 02/03/2022, the following components will be installed:

- Pipe elbow with hose clamps 56.01.979P



This has no impact on the function of the units.

NOTE:

Further information can be found in MI_2206: Pipe elbow with hose clamps floor unit – removal and installation.



LINK MI_2206